


IIHS Split Screen Incorrect and Correct Installation at Simulated 35 mph. April 12, 2012

Incorrect Installation without Tether



Correct Installation with Tether

